

**UT382**
[Enlarge](#)
[Download Manual](#)
[Download Software](#)
**Luminometers****SPECIFICATIONS**

Basic Functions		Range	Best Accuracy
Illuminance Measurement	LUX	20 Lux	±(3%+20)
		200 Lux	±(3%+8)
		2000 Lux	±(3%+8)
		20000 Lux	±(3%+8)
Illuminance Measurement	CD	2CD	
		20CD	
		200CD	
		2000CD	
<b>Special Functions</b>			
Data Hold	Display"HOLD"	✓	
Illuminance Measurement	Display "Lux/CD"	✓	
Max / Min Mode	Display "Max" or " Min"	✓	
Sleep Mode	Around 10 Minutes	✓	
Low Battery Display	Around < 7.1V	✓	
Data Logging		✓	
Auto Ranging		✓	
Real Time Clock		✓	
Working Temperature	0°C~40°C(32°F~104°F)	✓	
Deposited Temperature	-10°C~55°C(14°F~122°F)	✓	
Relative Humidity	≤7.5%	✓	
USB		✓	

**GENERAL CHARACTERISTICS**

Power	9V Alkaline Battery x 1
LCD Size	22.5 x 32.5mm
Product Colour	Red and Grey
Product Net Weight	185g
Product Size	195 x 45 x 26mm
Standard Accessories	USB Interface Cable,CD, English Manual, Carrying Bag, Battery
Standard Individual Packing	Blister
Standard Quantity Per Carton	40 pcs
Standard Carton Measurement	650 x 560 x 300mm (0.11 CBM Per Standard Carton)
Standard Carton Gross Weight	15kg

\*Available at Extra Cost

Specifications and other information are subject to change without further notice.

[Back to main menu](#)